

DATE 2019-10-24	TECHNICIAN Darren Mann	JOB/ORDER # 9708	REFERENCE TEXT Client reference
FIRST NAME David	LAST NAME Gadd		
BILLING ADDRESS COMPANY / BILLING NAME 306 - 1465 COMOX ST VANCOUVER, V6G1N9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 306 - 1465 COMOX ST, BUZZER 306 VANCOUVER, V6G1N9 BRITISH COLUMBIA, CANADA	
PHONE 604.710.0546		EMAIL gaddzeit@gmail.com	

REASON FOR TODAY'S CALL:

Bathroom sink is not draining correctly. When water pours for a few seconds, it begins to back up. It then drains slowly, taking about 60-90 seconds.

DESCRIPTION OF WORK PERFORMED:

I used a PowerSpin drain snake to clean the lavatory drain and tested by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Lavatory	\$139.00	\$139.00
SUBTOTAL:				\$139.00
GST (5%):				\$6.95
TOTAL:				\$145.95

Give us Feedback
Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2019-10-24

CUSTOMER SIGNATURE

DATE