

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2019-10-30	TECHNICIAN Darren Mann		JOB/ORDER # 9736		REFERENCE TEXT Client reference	
FIRST NAME Jason		LAST NAME King				
BILLING ADDRESS COMPANY / BILLING NAME 1907 - 193 AQUARIUS MEWS VANCOUVER, V6Z 2Z2 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 1907 - 193 AQUARIUS MEWS, VANCOUVER, V6Z 2Z2 BRITISH COLUMBIA, CANADA		
PHONE 604.783.8741				EMAIL g8nigazi@hotmail.com		

REASON FOR TODAY'S CALL:

Thank You!

Install customer supplied lavatory faucet.

DESCRIPTION OF WORK PERFORMED:

I installed the new lavatory faucet and pop-up drain assembly. Tested by filling and draining the sink multiple times.

CHARGES, E. & O. E.

QTY.	CODE	DESCRIPTION				PRICE
1	Y //	Replace Single Hole	e Hole Lavatory Faucet - CUSTOMER SUPPLIED			\$159.00
<i>Q</i>		and and	RANTY: PARTS - SUBJECT TO MANUFACTUR	<u>PARTS</u> - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
	Gwe us Feedback Please visit our feedback page at:		<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 MAINTENANCE IS NOT DONE ON NEV	GST (5%):	\$7.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.			WARRANTY ON CUSTOMER SUPPLIE	TOTAL:	\$166.95	
		,	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES			7

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2019-10-30

DATE