

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2019-11-05	TECHNICIAN Darren Mann		JOB/ORD 9755	DER#	REFERENCE TEXT 19-1563
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1801 - 1495 RICHARDS ST GABRIELA KACZKA: 1-236-868-3204 BOYFRIEND: 1.236.862.0009 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				MAIL ndrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Kitchen Garburator: No longer working, looks like it has cracks, photo attached

DESCRIPTION OF WORK PERFORMED:

The garburator housing was cracked and leaking. I replaced the garburator with new and tested by filling and draining both sides of the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Supply & Install 1/2HP Badger5 Garburator	\$329.00	\$329.00
Ruse	SUBTOTAL:	\$329.00		
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$16.45
		.com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$345.45
invoice and	tell us how the state of the st	We did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLETED DETERIORATION OF LEAD PURES SIXTURES OF ANNOTINES DAMAGES.		

2019-11-05