

2019-11-29

DATE

HST #837181627

DATE 2019-11-29	TECHNICIAN Darren Mann		JOB/O 9810	RDER#	REFERENCE TEXT				
FIRST NAME Office		LAST NAME Admin (Millson	Technol	ogies)					
BILLING ADDRESS MILLSON TECHNOLOGIES 2036 COLUMBIA ST VANCOUVER, V5Y3E1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2036 COLUMBIA ST VANCOUVER, V5Y3E1 BRITISH COLUMBIA, CANADA	4				
PHONE 604.707.0414				EMAIL accounting@millson.net					

REASON FOR TODAY'S CALL:

Shop sink: Leaking from drain and faucet loose.

DESCRIPTION OF WORK PERFORMED:

The beveled washer within the slip joint adaptor was broken and the drainage was detaching from the sinks tailpiece. I replaced the broken washer and used a bent

QTY.	CODE		UNIT PRICE	PRICE	
1		Discount Labour		\$99.00	\$99.00
Qo	(1	eodlack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
Gwe us Teedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
			INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE