



DATE 2019-12-05	TECHNICIAN Darren Mann	JOB/ORDER # 9817	REFERENCE TEXT Client reference
FIRST NAME Chris		LAST NAME Marchesi	
BILLING ADDRESS COMPANY / BILLING NAME 1503 - 1001 RICHARDS ST VANCOUVER, V6B 1J6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1503 - 1001 RICHARDS ST, BUZZER 2614 VANCOUVER, V6B 1J6 BRITISH COLUMBIA, CANADA	
PHONE 604.616.5061		EMAIL chrism@vanclueverttech.com	

REASON FOR TODAY'S CALL:  
Shower valve cartridge broken.

DESCRIPTION OF WORK PERFORMED:  
I replaced the broken shower valve mixing cartridge and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Cartridges HC44	\$209.00	\$209.00
SUBTOTAL:			\$209.00	\$209.00
GST (5%):			\$10.45	\$10.45
TOTAL:			\$219.45	\$219.45

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2019-12-05

CUSTOMER SIGNATURE

DATE