



DATE 2019-12-18	TECHNICIAN Darren Mann	JOB/ORDER # 9828	REFERENCE TEXT Client reference
FIRST NAME Yuri		LAST NAME Stratton	
BILLING ADDRESS COMPANY / BILLING NAME 3532 BLENHEIM VANCOUVER , V6L2X9 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3532 BLENHEIM VANCOUVER , V6L2X9 BRITISH COLUMBIA, CANADA	
PHONE 604.364.6862		EMAIL yuririabadillo@hotmail.com	

REASON FOR TODAY'S CALL:
Leak under kitchen sink.

DESCRIPTION OF WORK PERFORMED:
The ABS drain slipjoint adaptor fitting was not glued to the drain. I glued this fitting and tested by filling and draining the sink multiple times. I noticed during testing that the kitchen faucet spray hose was tangled up around the water filter piping. I disconnected the faucet spray hose, untangled it, then reconnected and tested again by filling and draining the sink multiple times.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1.25		Labour	\$109.00	\$136.25
			SUBTOTAL:	\$136.25
			GST (5%):	\$6.81
			TOTAL:	\$143.06

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2019-12-18

 CUSTOMER SIGNATURE

 DATE