

(B) @SimplyPlumbing ff YaletownPlumbing

HST #837181627

DATE 2019-12-30	TECHNICIAN Darren Mann		JOB/O 9844	RDER #	REFERENCE TEXT Client reference
FIRST NAME Cassandra		LAST NAME Wong	97		
BILLING ADDRESS COMPANY / BILLING NAME 602 - 535 SMITHE ST VANCOUVER, V6B0H2 BRITISH COLUMBIA, CANADA		<i>1</i> 2	4	SERVICE ADDRESS 602 - 535 SMITHE ST, BUZZEF CANDICE: 778.987.5775 VANCOUVER, V6B0H2 BRITISH COLUMBIA, CANADA	
PHONE tsao.melissa@gmail.com				EMAIL danheff@gmail.com	

REASON FOR TODAY'S CALL:

Garburator leaking.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking right through the bottom and could not be repaired. I replaced the garburator with new and tested by filling and draining the sink while

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE	
1		Supply & Install 1/2HP Badger5 Garburator	\$329.00	\$329.00	
Rung	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$16.45	
		com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$345.45	
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED BUSTED DETERIORATION OR LEAD RIDES SIXTURES OF EARLOUTS AND ANY OTHER DAMAGES.			

CUSTOMER SIGNATURE

DATE