

DATE

HST #837181627

DATE 2020-01-06	TECHNICIAN Darren Mann		JOB/O 9868	RDER #	REFERENCE TEXT Client reference
FIRST NAME Indre		LAST NAME Sakus			
BILLING ADDRESS COMPANY / BILLING NAME 1503 - 1863 ALBERNI ST VANCVOUER, V6G 3H8 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  1503 - 1863 ALBERNI ST, BUZ VANCVOUER, V6G 3H8 BRITISH COLUMBIA, CANADA	
PHONE 604.655.8923				EMAIL isakus@hotmail.com	

## REASON FOR TODAY'S CALL:

Garburator doesn't work. Only a slight humming sound is heard when turned on. And little sink beside dishwasher fills up and doesn't drain properly when dishwasher is in use. Must be a clog somewhere.

## DESCRIPTION OF WORK PERFORMED:

I was able to get the garburator moving again by removing broken glass from within the garburator grinding chamber and tested by filling and draining the sink

QTY.	CODE		UNIT PRICE	PRICE	
1		Labour		\$109.00	\$109.00
Q	(1	warra	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$109.00
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$5.45
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  REST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$114.45
		We did.  MAD MAT SET RES TERI	E THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ETHAL SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND ERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ILED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES JULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  MS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK RGES. E. & O. E.		