



2012-06-26

DATE



HST #837181627

TECHNICIAN darren mann		JOB/ORDER # 286	REFERENCE TEXT	
	LAST NAME Bebek			
		SERVICE ADDRESS		
57 A		VANCOUVER, V6M6L6		
		EMAIL brianbebek@gmail.com		
	darren mann	darren mann LAST NAME Bebek	LAST NAME Bebek SERVICE ADDRESS #406 - 933 SEYMOUR I VANCOUVER, V6M6L6 BRITISH COLUMBIA, C	LAST NAME Bebek SERVICE ADDRESS #406 - 933 SEYMOUR ST BU#57 VANCOUVER, V6M6L6 BRITISH COLUMBIA, CANADA

REASON FOR TODAY'S CALL:

-tub drain clogged

DESCRIPTION OF WORK PERFORMED:

-snake tub drain. Pulled hair.

TECHNICIAN RECOMMENDATIONS:

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1 h 00 m		Labour (started at 2012-06-26 09:02 am)	\$99.00	\$99.00
<i>Q.</i>		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
	t our feedbac	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	HST (12%):	\$11.88
	ownplumbing equired detai	com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS. s from your	TOTAL:	\$110.88
invoice and	tell us how	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREI WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEI SETTLED RUSTED DETERIORATION OR LEAD PIECE SIXTURES. CLEAN QUITS AND ANY OTHER DAMA	l,	

CUSTOMER SIGNATURE