



DATE 2012-07-13 02:00 pm	TECHNICIAN Evan Brandle	JOB/ORDER # 354	REFERENCE TEXT
FIRST NAME Ricardo	LAST NAME Rosales		
BILLING ADDRESS  1606 - 1331 WEST GEORGIA BUZ#1681 VANCOUVER, V6E4P1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS  #1707 - 1189 MELVILLE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.386.4399		EMAIL ricardor@getgreenstar.com	

REASON FOR TODAY'S CALL:  
-garb jammed

DESCRIPTION OF WORK PERFORMED:  
-garburator was not plugged in. plugged in garburator, cleared out buildup of rust, and replaced cracked drain 90

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
1		Garburator Drain 90 Replacement Kit	\$8.00	\$8.00

SUBTOTAL:	\$107.00
HST (12%):	\$12.84
TOTAL:	\$119.84

## Give us Feedback

Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.

*Thank You!*

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

\_\_\_\_\_ 2012-07-16  
 CUSTOMER SIGNATURE DATE