



HST #837181627

DATE 2012-08-07	TECHNICIAN darren mann		JOB/ORDER # 491		REFERENCE TEXT Client reference		
FIRST NAME Wayne		LAST NAME Fritz	97				
BILLING ADDRESS COMPANY / BILLING NAME #1710 1001 RICHARDS ST BU VANCOUVER, V6B1J6 BRITISH COLUMBIA, CANADA		<u> </u>	Ų	#1710 1001 RICHARDS ST BU VANCOUVER, V6B1J6 BRITISH COLUMBIA, CANADA			
PHONE 604.345.8487				EMAIL wlfritz72@hotmail.com			

## REASON FOR TODAY'S CALL:

-remove shower trim

## **DESCRIPTION OF WORK PERFORMED:**

-made visit on the 7th and tried to remove shower trim/handle, could not due to corrosion of the set screw in the handle. tried to find replacement trim to avoid having to replace the whole valve but could not. -scheduled another appointment to replace shower valve. -made another visit on the 10th, cut out tile around old shower valve, removed old valve and replaced with new Delta shower valve.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Labour		\$99.00	\$99.00
1	11	Replacement of Shower Valve (Flat Rate - Labour & All Materials)		\$499.00	\$499.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$598.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		LABOUR	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	HST (12%):	\$71.76
		com/reedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$669.76

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES MATERIALS LISTED HE SETTLED, RUSTED, DE	LISTED ABOVE ARE SATISFACTORY C REON ARE CORRECT. YALETOWN PLU	MBING IS NOT RESPONSIBLE FOR BROKEN, RES, CLEAN OUTS AND ANY OTHER DAMAGES
TERMS: NET CASH THE	AMOUNTS CONTAINED HEREIN ARE F	FOR LABOUR, MATERIALS AND TRUCK
CHARGES. E. & O. E.		
		2012-08-07
		20.2 00 07
	CUSTOMER SIGNATURE	DATE