





HST #837181627

DATE 2012-10-11	TECHNICIAN Kristian Evans		JOB/O 753	RDER #	REFERENCE TEXT Client reference
FIRST NAME Shirley		LAST NAME			
BILLING ADDRESS CRERAR DEVELOPMENT CORPORATION 938 HOWE ST 11TH FLOOR VANCOUVER, V6Z1N9 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 548 BEATTY ST VANCOUVER, V6Z1N9 BRITISH COLUMBIA, CANADA	
PHONE 604.484.1647				EMAIL shirley@crerar.ca	

REASON FOR TODAY'S CALL:

-one toilet non-stop flushing -one toilet frequently plugging up.

DESCRIPTION OF WORK PERFORMED:

Replace flapper in woman's restroom. Snaked and replaced flapper and handle in men's restroom toilet

QTY.	CODE		UNIT PRICE	PRICE	
2	2398043	GP84995 FLAPPER ASSM KIT			\$30.00
1.5	<i>I</i> .	Labour		\$99.00	\$148.50
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Interest at the legal rate is charged on past due accounts. Acknowledgement is made that services listed above are satisfactory completed and that charges at materials listed hereon are correct. Yaletown plumbing is not responsible for e settled, rusted, deterior are to reprince the properties of		oodlack	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$178.50
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	HST (12%):	\$21.42	
				TOTAL:	\$199.92
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES		

CUSTOMER SIGNATURE

2012-10-11