





HST #837181627

DATE 2012-10-12	TECHNICIAN Kristian Evans		JOB/ORDER # 759	REFERENCE TEXT Client reference	
FIRST NAME Jessica		LAST NAME Mcdonald			
BILLING ADDRESS COMPANY / BILLING NAME TH193 - 1228 MARINASIDE VANCOUVER, BRITISH COLUMBIA, CANADA			SERVICE ADDRESS TH193 - 1228 MARIN VANCOUVER, BRITISH COLUMBIA	IASIDE	
PHONE 604.376.8112			EMAIL jlmcdonald@uniserve	.com	

REASON FOR TODAY'S CALL:

-garb jammed

## **DESCRIPTION OF WORK PERFORMED:**

Remove and replace garbarator. Installed new badger 5 to replace existing waste king.

QTY.	CODE		UNIT PRICE	PRICE		
1 h 00 m	17/	Labour (started at 2012-10-12	\$99.00	\$99.00		
1	0660051	BADGER 5 ISE WASTE DISF	ISE WASTE DISP1/2HP			
Concrete Goodle of Warranty:			PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$264.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	HST (12%):	\$31.68	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$295.68	

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

 $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ 

CHARGES. E. & O. E.

2012-10-12

CUSTOMER SIGNATURE