



DATE 2012-11-28	TECHNICIAN Kristian Evans	JOB/ORDER # 942	REFERENCE TEXT
FIRST NAME Meredith	LAST NAME Mclean		
BILLING ADDRESS #605 - 1068 HORNBY ST BUZ#037 VANCOUVER, BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #605 - 1068 HORNBY ST BUZ#037 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.902.6877		EMAIL meredithmclean@hotmail.com	

REASON FOR TODAY'S CALL:
 -kitchen sink slow to drain. Water coming up opposite side of sink when garburator turned on.

DESCRIPTION OF WORK PERFORMED:
 Unclogged kitchen sink. Recommended a new garb, customer agreed. Removed and replaced garb.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
1	0660051	BADGER 5 ISE WASTE DISP1/2HP	\$165.00	\$165.00

SUBTOTAL:	\$264.00
HST (12%):	\$31.68
TOTAL:	\$295.68

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

meredithmclean

2012-11-28

CUSTOMER SIGNATURE

DATE