



DATE 2012-12-07	TECHNICIAN Kristian Evans	JOB/ORDER # 957	REFERENCE TEXT Client reference
FIRST NAME Romy	LAST NAME Buxton		
BILLING ADDRESS COMPANY / BILLING NAME 2496 WEST 5TH AVE VANCOUVER, V6K1S8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2496 WEST 5TH AVE VANCOUVER, V6K1S8 BRITISH COLUMBIA, CANADA	
PHONE 604.313.6607		EMAIL romybuxton@yahoo.ca	

REASON FOR TODAY'S CALL:

-remove tile around shower valve, replace shower valve. -shorten hight of tub drain overflow through access cut out of tile. -if we have enough time we will be replacing a second shower valve.

DESCRIPTION OF WORK PERFORMED:

-replaced two shower valves. -shortened overflow pipe using access we cut out to replace valve body.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
2		Replace Tub/Shower VLV	\$349.00	\$698.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$698.00
HST (12%):	\$83.76
TOTAL:	\$781.76

\_\_\_\_\_ 2012-12-07  
 CUSTOMER SIGNATURE DATE