



DATE 2013-01-08	TECHNICIAN darren mann	JOB/ORDER # 1099	REFERENCE TEXT Client reference
FIRST NAME Dave		LAST NAME Penfold	
BILLING ADDRESS COMPANY / BILLING NAME #1003 - 819 HAMILTON ST BUZ#198 VANCOUVER, V6B6M2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #1003 - 819 HAMILTON ST BUZ#198 VANCOUVER, V6B6M2 BRITISH COLUMBIA, CANADA	
PHONE 778.898.4200		EMAIL davepenfold@gmail.com	

REASON FOR TODAY'S CALL:
-garburator leaking

DESCRIPTION OF WORK PERFORMED:
-replaced garburator

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
1	0660051	BADGER 5 ISE WASTE DISP1/2HP	\$165.00	\$165.00

SUBTOTAL:	\$264.00
HST (12%):	\$31.68
TOTAL:	\$295.68

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2013-01-08

CUSTOMER SIGNATURE

DATE