



HST #837181627

DATE 2013-01-10	TECHNICIAN Kristian Evans		JOB/ORDER # 1117	REFERENCE TEXT Client reference	
FIRST NAME Rod		LAST NAME Santos		·	
BILLING ADDRESS COMPANY / BILLING NAME 6151 OAK ST VANCOUVER, V6M2W3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 6151 OAK ST VANCOUVER, V6M2W3 BRITISH COLUMBIA, CANADA		
PHONE 604.761.0633			EMAIL drsantos@shaw.ca		

REASON FOR TODAY'S CALL:

-garburator jammed.

DESCRIPTION OF WORK PERFORMED:

-Un jammed garbarator, inspected garb and looks to be in good shape. No rust on the plate.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1	y/	First Hr Outside of No Travel Time Service Area			\$148.50	\$148.50
Ruse	s G	oodlack	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$148.50
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		HST (12%):	\$17.82
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		TOTAL:			\$166.32	
		MADE THAT MATERIALS SETTLED, RI RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE

2013-01-10

DATE