



2013-01-18

DATE



HST #837181627

DATE 2013-01-18	TECHNICIAN darren mann		JOB/O 1150	RDER #	REFERENCE TEXT WO#4543	
FIRST NAME Andrea		LAST NAME Ferina	97			
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  #502 - 495 WEST 6TH AVE VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com		

## REASON FOR TODAY'S CALL:

-garburator jammed. (i was there in August for the same issue, that time it was a build up of rust and informed Stephanie to run it at least once a week to help prevent it from jamming up.)

## DESCRIPTION OF WORK PERFORMED:

-the garburator was jammed up due to a build up of rust. The tenant travels often and this time away allows the rust to form in the grinding chamber.

## TECHNICIAN RECOMMENDATIONS:

-Stephanie mentioned that she would be happy to have the garburator removed as she usually only runs it to help prevent it from jamming up.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	11	Discount Labour 89	\$89.00	\$89.00
<i>Q</i>	Give us Feedback Warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	HST (12%):	\$10.68
			TOTAL:	\$99.68
		We did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED BUSTED DETERIORATION OR LEAD RIDES ENTINESS CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE