





HST #837181627

| DATE 2013-02-13 | TECHNICIAN darren mann | | JOB/O 989 | RDER# | REFERENCE TEXT Client reference | |
|---|------------------------|----------------------|--------------|---|------------------------------------|--|
| FIRST NAME Carlo | | LAST NAME Donetti | | | | |
| BILLING ADDRESS SUTTON GROUP DEL MAR REALTY & PROPERTY MANAGEMENT #202 - 1118 HOMER ST VANCOUVER, V6B6L5 BRITISH COLUMBIA, CANADA | | | NT | SERVICE ADDRESS 1465 WEST HASTINGS VANCOUVER, BRITISH COLUMBIA, CANADA | | |
| PHONE 604.763.1063 | | | | EMAIL carlofran1@gmail.com | | |

REASON FOR TODAY'S CALL:

Thank You!

-replace toilet flush valve assembly.(supplied by homeowner)

DESCRIPTION OF WORK PERFORMED:

-remove toilet to access inside of tank. Replaced fillvalve, supply, and flush valve assembly.

| QTY. | CODE | DESCRIPTION | UNIT PRICE | PRICE |
|---|--|---|--|----------|
| 2 | 1 | Discount Labour 89 | \$89.00 | \$178.00 |
| <i>Q.</i> | Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY | | | |
| Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. | | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID | ` ' | \$21.36 |
| | | | TOTAL: | \$199.36 |
| | | ve did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT R SETTLED RUSTED DETERIORATION OR LEAD PIPES SIXTURES CLEAN OUT | THAT CHARGES AND ESPONSIBLE FOR BROKEN, | |

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

CHARGES, E. & O. E.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2013-02-13

DATE