





UNIT PRICE

HST #837181627

DATE 2013-03-05	TECHNICIAN darren mann	Way.	JOB/ORDER # 1340	REFERENCE TEXT Client reference	
FIRST NAME Daniel		LAST NAME Poncelat			
BILLING ADDRESS DANIEL LE CHOCOLAT BELGE 88 E 7TH AVE VANCOUVER, V5T1M2 BRITISH COLUMBIA, CANADA			SERVICE ADDRES  UNIT 822 - PARK I  VANCOUVER,  BRITISH COLUMB	ROYAL NORTH	
PHONE 604.879.7782			EMAIL dponcelet@telus.ne	et	

## REASON FOR TODAY'S CALL:

-toilet leaking

## **DESCRIPTION OF WORK PERFORMED:**

-found that the wax seal was broken. i lifted the toilet and installed a new Max Wax wax ring, re-set toilet and tested.

## TECHNICIAN RECOMMENDATIONS:

CODE

-i was called in for a leak on this same toilet in October of last year and replaced the parts that were leaking at the time. this wax ring wasn't leaking at the time but i've taken a 1/2 hour off of my time for this trip anyway:)

**DESCRIPTION** 

1	11	Discount Labour		\$89.00	\$89.00
1	9527271	ULTRAHD WAX SETTING	SETTING SEAL W/HRN		\$8.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$97.00	
	Please visit our feedback page at:  Labour - 1 Year on New UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		HST (12%):	\$11.64	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$108.64
		INTERE	EREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH	AT CHARCES AND
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES	
SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS A	ND ANY OTHER DAMAGES
RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE	RIALS AND TRUCK
CHARGES. E. & O. E.	
	2013-03-05
CUSTOMER SIGNATURE	DATE
GOSTOWIER SIGNATURE	DATE