



HST #837181627

DATE 2013-07-26	TECHNICIAN Kristian Evans		JOB/ORDER # 1954	REFERENCE TEXT Client reference	
FIRST NAME Mike		LAST NAME Drew			
BILLING ADDRESS COMPANY / BILLING NAME #2301 - 1495 RICHARDS ST BUZ#1155 VANCOUVER, V6Z3E3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  2301 - 1495 RICHARDS ST BUZZER: 1155 VANCOUVER, V6Z3E3 BRITISH COLUMBIA, CANADA		
PHONE 604.616.0112			EMAIL mikedrew_12@hotma	EMAIL mikedrew_12@hotmail.com	

## REASON FOR TODAY'S CALL:

## DESCRIPTION OF WORK PERFORMED:

Un jammed garbarator, bager 5 looks to be in good condition.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Free Locked Up Garbu	rator or Clear Simple Obstruction	\$99.00	\$99.00
Runo	Gwe us Feedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
www.yaletownplumbing.com/feedback [1]			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		, IN	ITEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY ADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2013-07-26

CUSTOMER SIGNATURE DATE

<sup>&</sup>quot;My Garberator stoped working. The sink now fills up and the dishwasher backs up into same sink."