





HST #837181627

DATE 2013-09-03	TECHNICIAN Kristian Evans		JOB/ORDER # 2105	REFERENCE TEXT Client reference	
FIRST NAME Roy		LAST NAME Funk			
BILLING ADDRESS COMPANY / BILLING NAME #2103 - 1438 RICHARDS BUZ#1139 VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANADA		#2103 - 1438 RI VANCOUVER, \	SERVICE ADDRESS  #2103 - 1438 RICHARDS BUZ#1139 VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANADA		
PHONE 604.561.9622 C		EMAIL royfunk@shaw.c	EMAIL royfunk@shaw.ca		

## REASON FOR TODAY'S CALL:

1) replace garbarator under kitchen sink 2) running toilet - stops if I lift lid and lift handle - seems to re-seat. assembly may need replacement

## **DESCRIPTION OF WORK PERFORMED:**

-Replace garbarator. -replace fill valve, flapper and supply line in ensuit bathroom.

QTY.	CODE	DESCRIPTION			PRICE
1	17/	Supply & Install 1/2HP Badge	\$299.00	\$299.00	
1	1	Replace Toilet Fill-Valve, Fla	\$119.00	\$119.00	
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$418.00
				GST (5%):	\$20.90
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$438.90

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2013-09-03

CUSTOMER SIGNATURE