

YALETOWN PLUMBING SERVICES LTD 1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com



2013-09-04

DATE

HST #837181627

DATE 2013-09-04	TECHNICIAN Darren Mann		JOB/ORDER # 2113	REFERENCE TEXT Client reference	
FIRST NAME Jennifer		LAST NAME Kendall		·	
BILLING ADDRESS COMPANY / BILLING NAME #507 - 928 RICHARDS ST BUZ#810 VANCOUVER, V6B6P6 BRITISH COLUMBIA, CANADA		79	#507 - 928 RICHARD VANCOUVER, V6B6F	SERVICE ADDRESS #507 - 928 RICHARDS ST BUZ#810 VANCOUVER, V6B6P6 BRITISH COLUMBIA, CANADA	
PHONE 604.683.1653			EMAIL jenniferk100@hotmail	EMAIL jenniferk100@hotmail.com	

REASON FOR TODAY'S CALL:

-replace Moen Posi-temp trim and handle

DESCRIPTION OF WORK PERFORMED:

-ordered and replaced Moen Positemp trim and handle.

TECHNICIAN RECOMMENDATIONS:

-we recently cleared hair from tub drain and this drain was slow to drain again. I ran our PowerSpin drain snake down the overflow and pulled a small amount of hair and a little metal spring which cleared the drain instantly. The PowerSpin was grabbing onto something larger at times that could not be pulled out. I tried this for 40 minutes and each time the snake grabbed on it would not pull out. It was mentioned that the homeowner attempted to use a drain snake they had purchased from Canadian tire that had a piece break off the tip. This tip will not come out using a drain snake. I suggest using a tub drain hair screen to prevent hair from collecting on the piece stuck in the ptrap. to remove this piece all together i suggest accessing the ptrap from the ceiling of the unit below and removing this piece that way.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	H.A.	Replace Shower Valve Trim - PosiTemp		\$129.00
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		s from your	TOTAL:	\$135.45
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE