

2013-09-30

HST #837181627

DATE 2013-09-30	TECHNICIAN Christopher Ryz		JOB/ORDER # 2260		REFERENCE TEXT Client reference				
FIRST NAME Hossein		LAST NAME Malek							
BILLING ADDRESS COMPANY / BILLING NAME 2596 PALMERSTON AVE WEST VANCOUVER, V7V2W5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  1303 - 1055 HOMER ST BUZ#1414  JASON: 604.726.7147  VANCOUVER,  BRITISH COLUMBIA, CANADA					
PHONE 778.891.3242				EMAIL hossein.malek@gmail.com					

## REASON FOR TODAY'S CALL:

-leak under kitchen sink. ---i'll invoice this one. ---call Jason when you are on your way.

## DESCRIPTION OF WORK PERFORMED:

-the strapping holding the kitchen sink to the underside of the counter had come loose and the wooden bracket on the right side under the ks was not secured. this caused the silicone to detach from the sink. -removed old silicone, installed two large L brackets under sink to hold and secure. re siliconed and tightened existing strapping and installed bracket on properly.

QTY.	CODE	DESCRIPTION			PRICE
1.5	/	Labour		\$99.00	\$148.50
Gwe us Feedback			IARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$148.50
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.43
		ls from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$155.93
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		