

HST #837181627

DATE 2013-10-08	TECHNICIAN Christopher Ryz		JOB/ORDER # 2307	REFERENCE TEXT Client reference	
FIRST NAME Paul		LAST NAME Sneah		·	
BILLING ADDRESS COMPANY / BILLING NAME 408 - 1850 COMOX ST BUZ#142 VANCOUVER, V6G1R3 BRITISH COLUMBIA, CANADA			408 - 1850 COMOX VANCOUVER, V6G1	SERVICE ADDRESS  408 - 1850 COMOX ST BUZ#142 VANCOUVER, V6G1R3 BRITISH COLUMBIA, CANADA	
PHONE 604.700.7340			EMAIL sneah849@gmail.co	m	

## REASON FOR TODAY'S CALL:

-toilet blockage, possible hard object dropped in toilet.

## **DESCRIPTION OF WORK PERFORMED:**

-used toilet auger to push object into main ....

QTY.	CODE	DESCRIPTION			PRICE
1		Clear toilet blockage usi	ckage using 6' toilet auger		\$139.00
Gwe us Feedback WARRANTY:		ware	NANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
	Please visit our feedback page at:		<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$145.95

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

2013-10-08

DATE

CUSTOMER SIGNATURE