

DATE 2013-11-07	TECHNICIAN Darren Mann	JOB/ORDER # 2476	REFERENCE TEXT Client reference
FIRST NAME Sophia		LAST NAME Szeto	
BILLING ADDRESS COMPANY / BILLING NAME 518 - 22 EAST CORDOVA STREET BUZ#0108 VANCOUVER, V6A 4G8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 518 - 22 EAST CORDOVA STREET BUZ#0108 VANCOUVER, V6A 4G8 BRITISH COLUMBIA, CANADA	
PHONE 604.837.8368		EMAIL sophbox@hotmail.com	

REASON FOR TODAY'S CALL:
-no water pressure on hot side of shower valve.

DESCRIPTION OF WORK PERFORMED:
-coordinated water shut down with Doug(building manager) and repaired both hot and cold integral stops. -tried to replace tub drain trim but could not remove the old drain, even with the Ridgid removal tool. This old drain will need to be cut out if replacement needed in the future.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Shower VLV Integral Stop	\$149.00	\$149.00

Give us Feedback


Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

	2013-11-07
_____ CUSTOMER SIGNATURE	_____ DATE

SUBTOTAL:	\$149.00
GST (5%):	\$7.45
TOTAL:	\$156.45