

DATE 2013-11-12	TECHNICIAN Christopher Ryz	JOB/ORDER # 2491	REFERENCE TEXT Client reference
FIRST NAME Macully		LAST NAME Clayton	
BILLING ADDRESS COMPANY / BILLING NAME 311 - 1018 CAMBIE ST BUZ#1320 VANCOUVER, V6B6J6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 311 - 1018 CAMBIE ST BUZ#1320 VANCOUVER, V6B6J6 BRITISH COLUMBIA, CANADA	
PHONE 604.312.1161		EMAIL macully.clayton@gmail.com	

REASON FOR TODAY'S CALL:

-Customer installed a new American Standard Studio Dual Flush Concealed Trapway toilet a few weeks ago and is getting a slow leak of smelly water dripping out of the back at the base of the toilet. The water is pooling there approximately twice a day.

DESCRIPTION OF WORK PERFORMED:

-Removed toilet , noticed existing wax seal was crushed on the plastic hub , installed new wax seal as well as re siliconed.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Toilet removal & reinstallation	\$169.00	\$169.00

Give us Feedback

Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2013-11-12

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45