

Phone: 604.727.4484 yaletownplumbing.com



2013-11-14



HST #837181627

DATE 2013-11-14	TECHNICIAN Darren Mann		JOB/ORDER # 2488	REFERENCE TEXT Client reference	
FIRST NAME Cam		LAST NAME Bowman			
BILLING ADDRESS COMPANY / BILLING NAME 602 - 1501 HOWE ST BUZ#8058 VANCOUVER, V6Z2P8 BRITISH COLUMBIA, CANADA		- 19	602 - 1501 HOWE S VANCOUVER, V6Z	SERVICE ADDRESS 602 - 1501 HOWE ST BUZ#8058 VANCOUVER, V6Z2P8 BRITISH COLUMBIA, CANADA	
PHONE 778.233.4756		EMAIL dr.bowman@live.com	m		

REASON FOR TODAY'S CALL:

-replace cartridges in shower valve(Kohler). inspect low water pressure coming out of shower head. -bidet getting no water.

DESCRIPTION OF WORK PERFORMED:

MASTER BATHROOM---replaced Pressure Balance & Mixing cartridge. -replaced shower head(customer supplied

TECHNICIAN RECOMMENDATIONS:

QTY.	CODE	DESCRIPTION			PRICE
1	//	Replace Mixing & Pressure Balance Cartridges - Kohler			\$209.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$209.00	
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$10.45
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$219.45
		MATERIAL SETTLED, RESULTIN TERMS: N	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		