

DATE 2013-11-27	TECHNICIAN Darren Mann	JOB/ORDER # 2569	REFERENCE TEXT Client reference
FIRST NAME Lawrence		LAST NAME Keenan	
BILLING ADDRESS COMPANY / BILLING NAME 3801 - 1328 WEST PENDER ST BUZ#3801 VANCOUVER, V6E4T1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 3801 - 1328 WEST PENDER ST BUZ#3801 VANCOUVER, V6E4T1 BRITISH COLUMBIA, CANADA	
PHONE 604.763.2754		EMAIL lawrence@csl.com	

REASON FOR TODAY'S CALL:  
-garb jammed

DESCRIPTION OF WORK PERFORMED:  
-removed piece of glass from grinding chamber and tested.

TECHNICIAN RECOMMENDATIONS:  
-the garburator is in good working order but I can see deterioration in the grinding chamber.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00

## Give us Feedback

Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
Fill in the required details from your invoice and tell us how we did.


Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2013-11-27

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95