

Phone: 604.727.4484 yaletownplumbing.com





2013-12-05



HST #837181627

DATE 2013-12-05	TECHNICIAN Darren Mann		JOB/O 2628	RDER #	REFERENCE TEXT Client reference	
FIRST NAME Alan		LAST NAME Nixon	97			
BILLING ADDRESS DOMINIONGRAND REALTY 2000 - 1500 WEST GEORGIA ST VANCOUVER, V6G2Z6 BRITISH COLUMBIA, CANADA		4	SERVICE ADDRESS  4722 WEST 2ND AVE HANS(TENANT): 604.417.5350 NATASHA(TENANT):604.365.1955 VANCOUVER, BRITISH COLUMBIA, CANADA			
PHONE 604.644.7756	=			EMAIL ajnixon@shaw.ca		

## REASON FOR TODAY'S CALL:

-water pooling around base of toilet.

## DESCRIPTION OF WORK PERFORMED:

-the toilet fill valve was not functioning properly. the water level would rise above the flood level rim of the overflow tube and leak out of where the toilet lever handle attaches to the tank. -i replaced the toilet fill valve, flapper, and supply. i also lowered the height of the overflow tube as it was set too high.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//.	Replace Toilet Fill-Valve, Flapper, Supply - Standard	\$169.00	\$169.00
Ruse	I	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS I		\$8.45
		s from your	TOTAL:	\$177.45
		Ve did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR  SETTLED, RUSTED DETERIORATION OR LEAD PIPES EXTURES. CLEAN OUTS AND ANY OTHER	AND R BROKEN, ER DAMAGES	