

Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-01-23	TECHNICIAN Darren Mann		JOB/ORDER # 2862	REFERENCE TEXT		
FIRST NAME Ken		LAST NAME Ekdahl				
BILLING ADDRESS		SERVICE ADDRESS	SERVICE ADDRESS			
208 - 1808 WEST 1ST AVE VANCOUVER, BRITISH COLUMBIA, CANADA			GWEN(TENANT): 1.5 LYNNE(PM): 778.988 VANCOUVER,	208 - 1808 WEST 1ST AVE GWEN(TENANT): 1.519.375.2485 LYNNE(PM): 778.988.1740 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.218.5956		EMAIL kenekdahl@gmail.cor	EMAIL kenekdahl@gmail.com			

## REASON FOR TODAY'S CALL:

-garburator not working. Gwen's mom will be waiting in the lobby. buzzer under "Ken Ekdahl"

## DESCRIPTION OF WORK PERFORMED:

-unjammed garburator and reset the breaker.

## TECHNICIAN RECOMMENDATIONS:

-the grinding chamber of the garburator is quite deteriorated. if the garburator jams up again i recommend replacing it.

QTY.	CODE	DESCRIPTION			PRICE
1		Labour - Pro Boner	3	\$0.00	\$0.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$0.00		
Please visit our feedback page at:		k page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$0.00

www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.

Thank You!

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2014-01-23 CUSTOMER SIGNATURE DATE