



SUBTOTAL: \$0.00

\$0.00

TOTAL:

HST #837181627

DATE 2014-02-06	TECHNICIAN Darren Mann	000	JOB/0 2924	RDER #	REFERENCE TEXT	
FIRST NAME Cynthia		LAST NAME Grant	207			
BILLING ADDRESS COMPANY / BILLING N 2308 - 977 MAINLAND VANCOUVER, V6B 1T2 BRITISH COLUMBIA, C	ST BUZ#7216 2		14	SERVICE ADDRESS 2308 - 977 MAINLAN BUZZER: 7216 VANCOUVER, V6B 1 BRITISH COLUMBIA	D ST BUZ#7216 T2	
PHONE 604.996.2800				EMAIL cynthia.grant@outloo	k.com	

REASON FOR TODAY'S CALL:

Bathtub not draining (again). *drain was snaked in September/2013

DESCRIPTION OF WORK PERFORMED:

-snaked small amount of hair from drain. it seems as though there may be some type of hard object down the drainage that our drain snake cannot grab onto. if there is an object down the drain small amounts of hair could potentially cling onto it and cause slow drainage in the future.

TECHNICIAN RECOMMENDATIONS:

-i recommend using a hair screen on the drain to help prevent hair from finding its way into the drainage. -the only way i see to remove an object that may be in the drainage would be to access the drainage from the ceiling below.

Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did.	INTEREST AT	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTI MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWN. SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THA	ADE, ABSOLUTELY NO LEDGEMENT IS HEREBY LT CHARGES AND
Thank You!	SETTLED, RU RESULTING F	STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AN FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER	ND ANY OTHER DAMAGES
		CUSTOMER SIGNATURE	2014-02-06 DATE