

YALETOWN PLUMBING SERVICES LTD 1503-1255 Seymour St. Vancouver, BC V6B 0H1 INVOICE Phone: 604.727.4484 yaletownplumbing.com

(E) @SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2014-04-04	TECHNICIAN Darren Mann		JOB/O 3085	RDER #	REFERENCE TEXT Client reference
FIRST NAME DAVE		LAST NAME BEDWELL	7		
BILLING ADDRESS COMPANY / BILLING NAME 1863 ALBERNI STREET VANCOUVER , V6G3H8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 302 - 1863 ALBERNI STREET BUZZER: 011 VANCOUVER , V6G3H8 BRITISH COLUMBIA, CANADA	
PHONE 604.351.6806				EMAIL dbedwell@cosco-usa.com	

REASON FOR TODAY'S CALL:

A leak from the T valve connection under the bathroom sink, \*call when you are 10 minutes away. \*Dave has received parts from Grohe.

## DESCRIPTION OF WORK PERFORMED:

-replaced integral supply tubes on Grohe lavatory faucet in master(left faucet). -replaced rubber washer in aerator(left faucet).

QTY.	CODE	DESCRIPTION				PRICE
1		Labour	7		\$99.00	\$99.00
Guve us Geedback   Please visit our feedback page at:   www.yaletownplumbing.com/feedback   [1]   Fill in the required details from your   invoice and tell us how we did.   Thank You!		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00	
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95		
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95	
		MATERIALS I SETTLED, RU RESULTING I	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK . & O. E. 2014-04-04 CUSTOMER SIGNATURE			