



2014-04-24

DATE



HST #837181627

DATE 2014-04-24	TECHNICIAN Darren Mann		JOB/ORDER # 3251	REFERENCE TEXT Client reference	
FIRST NAME Suzan		LAST NAME Sadeghi			
BILLING ADDRESS COMPANY / BILLING NAME 1438 RICHARDS ST VANCOUVER, V6Z3B8 BRITISH COLUMBIA, CANADA			#708 - 1438 RICHAF VANCOUVER, V623 BRITISH COLUMBIA	RDS ST, BUZZER 1039 BB8	
PHONE 604.633.0358			EMAIL suzansadeghi@outlo	ook.com	

REASON FOR TODAY'S CALL:

-replace shower cartridge(Cascade)

DESCRIPTION OF WORK PERFORMED:

I replaced the mixing and pressure balancing cartridges within the shower valve(Cascade). The old screw holding the handle in place was rusted and could not be reused, I used a screw out of our van stock that is holding the handle tight.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Mixing & Pressure Balance Cartridge - HC180		\$189.00	\$189.00
<i>Q</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$189.00	
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$9.45
www.yaletownplumbing.com/feedback [1] Fill in the required details from your		s from your			\$198.45
invoice and tell us how we did. Thank You!		We did. MATE SETTI RESU TERM	EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND RIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES LTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. §: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK GES. E. & O. E.		

CUSTOMER SIGNATURE