

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-06-12	TECHNICIAN Darren Mann		JOB/O 3440	RDER #	REFERENCE TEXT Client reference
FIRST NAME Yvonne		LAST NAME Mejia			
BILLING ADDRESS COMPANY / BILLING NAME 501 PACIFIC ST VANCOUVER, V6Z2X6 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS #2507 - 501 PACIFIC ST VANCOUVER, V6Z 2X6 BRITISH COLUMBIA, CANADA	
PHONE 1.818.207.2367				EMAIL ymejia@me.com	

REASON FOR TODAY'S CALL: Our garburator isn't working.

DESCRIPTION OF WORK PERFORMED:

The garburator grinding chamber was deteriorated, rusted parts of the grinding chamber plater were flaking off and there were holes in it. I replaced the garburator with a new Waste King 1001. Tested by filling and draining he sink 2 times.

QTY.	CODE		DESCRIPTION			
1	//	Supply & Install 1/2HP V	Supply & Install 1/2HP Waste King 1001 Garburator			
invoice and tell us how we did.		warr	ANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$279.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$13.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95	
		we did.	REST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY BETHAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND BEHALS LISTED LEBECAL ARE CARBEST, VALETOWAN BUMBING IS NOT DESPONSIBLE EACH BROWEN.			

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2014-06-12

CUSTOMER SIGNATURE

DATE