

## YALETOWN PLUMBING SERVICES LTD





HST #837181627

DATE 2014-07-24	TECHNICIAN Darren Mann		JOB/ORDER # 3594	REFERENCE TEXT Client reference		
FIRST NAME Steven		LAST NAME Schelling				
BILLING ADDRESS COMPANY / BILLING NAME 1020 HARWOOD VANCOUVER, BRITISH COLUMBIA, CANADA			#1003 - 1020 HARW VANCOUVER,	SERVICE ADDRESS  #1003 - 1020 HARWOOD, BUZZER #5301 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.671.9827			EMAIL sschelling@telus.net			

## REASON FOR TODAY'S CALL:

-supply and install 2 new soft close toilet seats(round front)

## DESCRIPTION OF WORK PERFORMED:

-replaced 2 toilet seats.

## **TECHNICIAN RECOMMENDATIONS:**

The cold handle of the master lavatory faucet was reported to be leaking. I had this faucet running for 5 minutes during the toilet seat replacement and found no leaking.

QTY.	CODE	DESCRIPTION			PRICE
1	11	Labour			\$99.00
2		Bemis 200SLOWT		\$52.00	\$104.00
<i>Q.</i> ,,,	(I	warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$203.00
	Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$10.15
				TOTAL:	\$213.15

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

2014-07-24 CUSTOMER SIGNATURE