

1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-07-29	TECHNICIAN Darren Mann		JOB/ORDER # 3609		REFERENCE TEXT Client reference
FIRST NAME Regan		LAST NAME Bosch			
BILLING ADDRESS COMPANY / BILLING NAME 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS  111 - 2040 CORNWALL ST CHRISTINA(TENANT): 778.323 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.908.0543				EMAIL regan@reganbosch.com	

## REASON FOR TODAY'S CALL:

-toilet tank not filling correctly.

## **DESCRIPTION OF WORK PERFORMED:**

The fillvalve was sticking and not properly filling the toilet tank and the 3" flapper had air bubbles forming on the rubber portion which was allowing water to slowly trickle through. I replaced the fillvalve, flapper, and supply line.

## TECHNICIAN RECOMMENDATIONS:

During testing I noticed the pex piping leading up to the WC shut off valve has a deep cut in it, it is not leaking but it could potentially leak in the future. Replacement is recommended. (I've sent a picture of this pex pipe in a separate email)

QTY.	CODE	DESCRIPTION		PRICE
1	116	Replace Toilet Fill-Valve, Flapper(3"), Supply - Discounted		\$149.00
1		After Hours Fee	\$50.00	\$50.00
<i>Q</i>	Construction of the second of		SUBTOTAL:	\$199.00
		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$9.95
			TOTAL:	\$208.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

	2014-07-29
CUSTOMER SIGNATURE	DATE