



HST #837181627

\$0.00

2014-08-20

DATE

| DATE 2014-08-20 | | | JOB/ORDER # 3684 | | REFERENCE TEXT Client reference | |
|---|----|-----------------------|---------------------|---|------------------------------------|--|
| FIRST NAME Daniel | | LAST NAME Poncelet | | | | |
| BILLING ADDRESS COMPANY / BILLING NAME 166 WEST 10TH AVE VANCOUVER, BRITISH COLUMBIA, CANAD |)A | 19 | 14 | SERVICE ADDRESS 166 WEST 10TH AVE VANCOUVER, BRITISH COLUMBIA, CANAI | DA . | |
| PHONE 604.873.3225 | | | | EMAIL dponcelet@telus.net | | |

REASON FOR TODAY'S CALL:

-smell of gas in kitchen and outside where gas line was run.

DESCRIPTION OF WORK PERFORMED:

Tested all connections on the outside of the house and in the crawl space. There was a small leak coming for the 90 connection just below the kitchen window. I tightened this connection and re-tested. I could not remove the stove as it was too heavy to move I my own.

SUBTOTAL: \$0.00 Gwe us Feedback PARTS - SUBJECT TO MANUFACTURER'S WARRANTY TOTAL: <u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO Please visit our feedback page at: WARRANTY ON CUSTOMER SUPPLIED MATERIALS. w.yaletownplumbing.com/feedback [1] Fill in the required details from your INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY invoice and tell us how we did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES <u> Thank You!</u> RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CUSTOMER SIGNATURE