

DATE 2014-09-10	TECHNICIAN Darren Mann	JOB/ORDER # 3786	REFERENCE TEXT Client reference
FIRST NAME kathleen	LAST NAME skinnider		
BILLING ADDRESS COMPANY / BILLING NAME 1252 HORNBY ST VANCOUVER, V6Z 0A3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 208 - 1252 HORNBY ST BUZZER: 1319 VANCOUVER, V6Z 0A3 BRITISH COLUMBIA, CANADA	
PHONE 778 233 6151		EMAIL kskinnider@gmail.com	

REASON FOR TODAY'S CALL:

"kitchen garburator is not working. was away for a month on holiday and when i came back no sound."

DESCRIPTION OF WORK PERFORMED:

The garburator seized up due to rust in the grinding chamber. I free'd up the grinding chamber and tested by filling and draining the sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00

## Give us Feedback

Please visit our feedback page at:

[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]

Fill in the required details from your invoice and tell us how we did.

## Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2014-09-10

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95