

DATE 2014-09-19	TECHNICIAN Darren Mann	JOB/ORDER # 3810	REFERENCE TEXT Client reference
FIRST NAME Govind Preet		LAST NAME Singh	
BILLING ADDRESS COMPANY / BILLING NAME 928 HOMER STREET VANCOUVER, V6B 1T7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2508 - 928 HOMER STREET VANCOUVER, V6B 1T7 BRITISH COLUMBIA, CANADA	
PHONE 604-376-5912		EMAIL govindpreetsingh@hotmail.com	

REASON FOR TODAY'S CALL:  
-garburator not working.

DESCRIPTION OF WORK PERFORMED:  
Replaced garburator with new Waste King 1001. Tested by filling and draining sink while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
			SUBTOTAL:	\$279.00
			GST (5%):	\$13.95
			TOTAL:	\$292.95

*Give us Feedback*

Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
Fill in the required details from your invoice and tell us how we did.

*Thank You!*

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2014-09-19

CUSTOMER SIGNATURE

DATE