

DATE 2014-09-19	TECHNICIAN Darren Mann	JOB/ORDER # 3840	REFERENCE TEXT Client reference
FIRST NAME Fern	LAST NAME Jeffries		
BILLING ADDRESS COMPANY / BILLING NAME TH1 - 63 KEEFER PLACE BUZ#7097 VANCOUVER, V6B 6N6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS TH1 - 63 KEEFER PLACE BUZ#7097 VANCOUVER, V6B 6N6 BRITISH COLUMBIA, CANADA	
PHONE 604.732.7097		EMAIL fern@me.com	

REASON FOR TODAY'S CALL:  
Bathroom drain plugged.

DESCRIPTION OF WORK PERFORMED:  
Used PowerSpin drain snake to clear hair from the shower drain and removed hair from the top of the tub drain.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
SUBTOTAL:				\$99.00
GST (5%):				\$4.95
TOTAL:				\$103.95

*Give us Feedback*

Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
Fill in the required details from your invoice and tell us how we did.

*Thank You!*

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2014-09-19

CUSTOMER SIGNATURE

DATE