





HST #837181627

DATE 2014-10-21	TECHNICIAN Darren Mann		JOB/ORDER # 3992		REFERENCE TEXT Client reference	
FIRST NAME Graham		LAST NAME Rawlings				
BILLING ADDRESS COMPANY / BILLING NAME 1490 PENNYFARTHING DRIVE VANCOUVER, V7J 4Z3 BRITISH COLUMBIA, CANADA			109 - 1 VANC	CE ADDRESS 490 PENNYFARTHING DUVER, V7J 4Z3 SH COLUMBIA, CANADA		
PHONE 604-224-3435			EMAIL grawlin	ngs@telus.net		

REASON FOR TODAY'S CALL: garburator leaking through unit.

DESCRIPTION OF WORK PERFORMED:

Replaced garburator with new Badger5. Replaced toilet fill valve and supply line.

QIT.	CODE		UNIT PRICE	PRICE		
1		Supply & Install 1/2HP Badge	\$299.00	\$299.00		
1		Replace Standard Fill-Valve	dard Fill-Valve - ADD-ON PRICING			
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$368.00	
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO		\$18.40	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$386.40	

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

CUSTOMER SIGNATURE