

DATE 2014-10-22	TECHNICIAN Darren Mann	JOB/ORDER # 3975	REFERENCE TEXT Client reference
FIRST NAME Irazu		LAST NAME Derby	
BILLING ADDRESS COMPANY / BILLING NAME 2890 WEST 13TH AVE VANCOUVER, V6K2T7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2890 WEST 13TH AVE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.668.4699		EMAIL irazud@gmail.com	

REASON FOR TODAY'S CALL:

-garburator leaking, appears to be coming from mounting bracket. -toilet running.

DESCRIPTION OF WORK PERFORMED:

POWDER ROOM---The FlushValve gasket had air bubbles in it causing water to slowly leak out of the tank into the bowl. I replaced this gasket and tested.GARBURATOR---The garburator mounting bracket had worked itself loose. I removed the mounting bracket and reinstalled. Tested by filling and draining the sink twice.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace FlushValve Gasket - Kohler	\$119.00	\$119.00
1		Re-Mount Garburator	\$50.00	\$50.00

Give us Feedback

Please visit our feedback page at:

www.yaletownplumbing.com/feedback [1]

Fill in the required details from your invoice and tell us how we did.

Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



CUSTOMER SIGNATURE

2014-10-22

DATE

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45