



DATE 2014-11-24	TECHNICIAN Darren Mann	JOB/ORDER # 4136	REFERENCE TEXT
FIRST NAME Cindy		LAST NAME Ross	
BILLING ADDRESS CINDY ROSS INTERIOR DESIGN 193 AQUARIUS MEWS VANCOUVER, V1Z3S4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2802 - 193 AQUARIUS MEWS BUZ#RUSH VANCOUVER, V1Z3S4 BRITISH COLUMBIA, CANADA	
PHONE 1.250.878.3331		EMAIL cindyross169@gmail.com	

REASON FOR TODAY'S CALL:
 Guest bathroom tub drain clogged.

DESCRIPTION OF WORK PERFORMED:
 Used PowerSpin drain snake to clear hair from guest bathroom tub drain. Tested by filling tub 8" and draining. I also cleared hair from the master bathroom tub and tested(free of charge).

TECHNICIAN RECOMMENDATIONS:
 The drain in the master bathroom is missing the lift rod, this rod also acts as a hair catcher so it would be a good idea to use a screen over the drain to help mitigate hair blockages.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clean drain using PowerSpin / Tub/Shower	\$139.00	\$139.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$139.00
GST (5%):	\$6.95
TOTAL:	\$145.95

_____ 2014-11-24

 CUSTOMER SIGNATURE DATE