



2015-01-13 DATE



HST #837181627

DATE 2015-01-13	TECHNICIAN Darren Mann		JOB/O 4253	RDER #	REFERENCE TEXT Client reference
FIRST NAME Denny		LAST NAME Seo			
BILLING ADDRESS COMPANY / BILLING NAME 5928 BIRNEY AVE VANCOUVER, V6S 0B5 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS #116 - 5928 BIRNEY AVE VANCOUVER, V6S 0B5 BRITISH COLUMBIA, CANADA	
PHONE 604 224 2661				EMAIL dennyhihi321@hotmail.com	

REASON FOR TODAY'S CALL:

"The attached are the pictures of the sink and the toilet. I can hear the low flow rate in the disposal unit under the sink. For the toilet, I can hear water leak sound underneath the top part of the flush buttons."

DESCRIPTION OF WORK PERFORMED:

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace Flush Valve	\$129.00	\$129.00	
Gwe us Feedback WARRANTY:			ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$135.45
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.		

CUSTOMER SIGNATURE