

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2015-03-04	TECHNICIAN Darren Mann		JOB/O 4488	RDER#	REFERENCE TEXT Client reference
FIRST NAME David		LAST NAME Holzer			
BILLING ADDRESS COMPANY / BILLING NAME 2330 MAPLE ST VANCOUVER, V6J 3T9 BRITISH COLUMBIA, CANADA		4	4	SERVICE ADDRESS  111 - 2330 MAPLE ST BUZ#111 VANCOUVER, V6J 3T9 BRITISH COLUMBIA, CANADA	
PHONE 7789862367				EMAIL davidgholzer@hotmail.com	

## REASON FOR TODAY'S CALL:

Ensuite: -leak coming from the bottom of the toilet -shower drain clogged

## DESCRIPTION OF WORK PERFORMED:

---Toilet: The leak was coming from the right side tank bolt, the bolt was loose and water was dripping down to the floor and under the toilet. I tightened the nut and tested by flushing multiple times. ---Shower: I used the PowerSpin drain snake to clear hair from the ensuite shower.

QTY.	CODE		UNIT PRICE	PRICE	
1		Clean drain using F	\$139.00	\$139.00	
<b>Gwe us Feedback</b> Please visit our feedback page at:			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$145.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE