





HST #837181627

DATE 2015-03-17	TECHNICIAN Darren Mann		JOB/ORDER # 4550		REFERENCE TEXT Client reference	
FIRST NAME Elaine		LAST NAME Biltzan	97			
BILLING ADDRESS COMPANY / BILLING NAME #1703 - 1005 BEACH AVE BUZ#1178 VANCOUVER, BRITISH COLUMBIA, CANADA			Ų	#1703 - 1005 BEACH AVE BUZ#1178 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.568.3593				EMAIL biltzans@shaw.ca		

REASON FOR TODAY'S CALL:

hank You!

Garburator not working.

## **DESCRIPTION OF WORK PERFORMED:**

The existing garburator had cracks in the housing and was non functional. I replaced the garburator with new and tested by filling and draining the sink while running the garburator.

QTY.	CODE		DESCRIPTION			PRICE
1		Supply & Install 1/2F	HP Badgers	\$299.00	\$299.00	
<i>Q.</i>	2 WARRANTY:		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$299.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$313.95	
		,	MADE THAT MATERIALS SETTLED, RI	T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.		

CUSTOMER SIGNATURE

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2015-03-17

DATE