

DATE 2015-03-27	TECHNICIAN Darren Mann	JOB/ORDER # 4597	REFERENCE TEXT Client reference
FIRST NAME Cova		LAST NAME Tatia	
BILLING ADDRESS COMPANY / BILLING NAME 508 - 111 WEST GEORGIA ST VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 508 - 111 WEST GEORGIA ST VANCOUVER, V6B1T8 BRITISH COLUMBIA, CANADA	
PHONE 604.632.0251		EMAIL covadongavilla@hotmail.com	

REASON FOR TODAY'S CALL:
garburator not working

DESCRIPTION OF WORK PERFORMED:

-The garburator was seized up due to build up of rust. I free'd the garburator by tapping out rust and tested by filling and draining the sink while running the garburator. -The lavatory drains were slow to drain, I removed hair from the stopper and tested by filling and draining the sinks.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00

Give us Feedback

Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
Fill in the required details from your invoice and tell us how we did.


Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



CUSTOMER SIGNATURE

2015-03-27

DATE

SUBTOTAL:	\$99.00
GST (5%):	\$4.95
TOTAL:	\$103.95