





HST #837181627

DATE 2015-04-07	TECHNICIAN Darren Mann		JOB/ORDER # 4626	REFERENCE TEXT Client reference			
FIRST NAME Eliza		LAST NAME Sukava					
BILLING ADDRESS COMPANY / BILLING NAME 1804 - 811 HELMCKEN ST VANCOUVER, V6Z1B1 BRITISH COLUMBIA, CANADA		1804 - 811 HELM VANCOUVER, V	SERVICE ADDRESS 1804 - 811 HELMCKEN ST BUZ#316 VANCOUVER, V6Z1B1 BRITISH COLUMBIA, CANADA				
PHONE 778.999.1580			EMAIL elizao@hotmail.co	om			

REASON FOR TODAY'S CALL:

leak coming from lavatory ABS drainage

DESCRIPTION OF WORK PERFORMED:

The slipjoint fitting under the lavatory sink was not piped in high enough and there was a slight gap between this fitting and the lavatory drain tail piece. I replaced the ptrap and slipjoint and tested by filling and draining the sink multiple times.

TECHNICIAN RECOMMENDATIONS:

The lavatory drainage is piped in with an s-trap. Eliza did not want to re-pipe this portion.

QTY.	CODE	DESCRIPTION			PRICE
1	11	Quoted Price		\$139.00	\$139.00
		and and war	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$139.00
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$145.95
		- Ir	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2015-04-07 CUSTOMER SIGNATURE DATE