

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2014-09-03	TECHNICIAN Darren Mann		JOB/ORDER # 3747		REFERENCE TEXT Client reference
FIRST NAME Tara		LAST NAME Zenon	7		
BILLING ADDRESS COMPANY / BILLING NAME 528 BEATTY STREET VANCOUVER, V6B 2L3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS #002 - 528 BEATTY STREET JORDAN(TENANT): 778.994.61 VANCOUVER, V6B 2L3 BRITISH COLUMBIA, CANADA	
PHONE 7789994420	~			EMAIL tarazenon@gmail.com	

REASON FOR TODAY'S CALL:

-leak under kitchen sink believed to be coming from drainage.

DESCRIPTION OF WORK PERFORMED:

-there were 2 loose connections, one on the drainage and one on the shut off valve located in the rear left side of the cabinet. i tightened these loose fittings and tested.

QTY .	CODE	DESCRIPTION				UNIT PRICE	PRICE
1		Labour	×			\$99.00	\$99.00
0		and had	WARRANTY:	: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$99.00
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE,		GST (5%):	\$4.95	
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$103.95	
		MATERIALS I SETTLED, RU RESULTING I	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RI JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA . & O. E.	ESPONSIBLE FOR BROKEN, S AND ANY OTHER DAMAGES			
				CUSTOMER SIGNATURE	DATE		